

Wist u dat....

Wouter Schouten Gerben ter Horst
November 2021

GEMBA
ASSETMANAGEMENT

IBM's and Gemba statements regarding its plans, directions, and intent are subject to change or withdrawal without notice at IBM's and Gemba's sole discretion. Information regarding potential future products is intended to outline our general product direction and it should not be relied on in making a purchasing decision. The information mentioned regarding potential future products is not a commitment, promise, or legal obligation to deliver any material, code or functionality. Information about potential future products may not be incorporated into any contract. The development, release, and timing of any future features or functionality described for our products remains at our sole discretion. Performance is based on measurements and projections using standard IBM benchmarks in a controlled environment. The actual throughput or performance that any user will experience will vary depending upon many factors, including considerations such as the amount of multiprogramming in the user's job stream, the I/O configuration, the storage configuration, and the workload processed. Therefore, no assurance can be given that an individual user will achieve results similar to those stated here.



IBM Control Desk volgende versie

GEMBA
ASSETMANAGEMENT

Nieuwe weergave volgens carbon design systeem

The screenshot displays the IBM Control Desk Service Requests interface. On the left, a sidebar contains navigation links for 'Available Queries' (All Records, All Bookmarks, All Service Requests) and 'Common Actions' (New Service Request, Change Status, Select Owner, Take Ownership, Create KPI, Service Request in queue, Service Request in progress, Pending Service Request, Resolve Service Request, Create Report). Below these are 'More Actions' (Attachment Library/Folders, Run Reports, Cognos Analytics).

The main area shows a table of Service Requests (1 - 20 of 139). The table has columns for Service Request, Summary, Reported By, Priority, Status, Owner, and Owner Group. The first few rows are:

Service Request	Summary	Reported By	Priority	Status	Owner	Owner Group
1001	Request for OS upgrade to Windows XP	LIBERI	4	QUEUED	CALDONE	
1002	Conference room is too hot	WINSTON	4	QUEUED		TIER1
1004	Keyboard Not Functioning - Desktop	LOU	1	RESOLVED		
1005	Laptop shows blue screen when I try to VPN.	WALL				
1006	Can't print from MS Word. Others software work fine.	JONES				
1007	Need MS SQL in my development computer.	MILLS				
1008	Error when printing Excel.	BOYD				
1015	Desktop shows blue screen when turned on.	LIBERI				
1016	Could you please send me URL to access the company Intranet?	LIBERI				
1017	How do I protect my computer from virus?	LIBERI				
1020	Desktop Performance Problems	SMITHERS				
1021	Printer out-of toner.	ROBERTS				
1022	I need to access ITSM folder in my Outlook. How do I do it?	SMITH				
1023	New employee setup.	MILLER				
1026	Move computer	PEDRICK				

On the right, the 'Create Service Request' form is shown. It includes fields for Reported By (GEMBA), Asset, Location, Configuration Item (AD34FG, Computer System), E-mail (w.schouten@gemba.nl), Reported Priority, Reported Date (28-10-21 11:55), Affected User (KAZMIER), and a Request Description. The 'Classify' section shows a classification of 2 \ 201 \ 20102 \ 2010202 and a class description of Request For Service \ IT \ New/Upgr Sftw \ Op System. The 'Attachments' section shows a document named 1020 with the description puzzelstukjes.jpg.

Jira Integratie



- Automatisch aanmaken van issues in Jira op basis van ICD incidenten.
- Status updates van Jira issues worden automatisch doorgezet naar IBM Control desk incidenten.
- Updates van beschrijving, prioriteit van een issue in Jira wordt doorgezet naar IBM Control Desk. Comments in Jira worden doorgezet als worklogs in IBM Control Desk incidenten.

Maximo competentie en trainings-management

GEMBA
ASSETMANAGEMENT

← List View Person Details Certificates Competencies Training

Person: ADAMS Display Name: Hank Adams Status: ACTIVE

Certificates Filter 1 - 2 of 2

Competencies	Description	Category	Status	Personal?
CORE	Core Values Competency	COMPETENCY	PROFICIENT	☒
BUILD	Building Teams Competency	COMPETENCY	EXPERT	☒


Details

Competencies: BUILD Building Teams Competency Status: EXPERT

Category: COMPETENCY Personal? ☒

Certificate	Certification Record
Certificate Acquired? ☒ Date of Certification: 10/20/21 Certificate: #Q35355433EC Certificate Expiration Date: 10/20/23	Certification: _____ Extension: _____ Expiry: _____

Select Permit and Certificate Type New Row



Scheduler

Graphical Resource View

Find Scenario

Find Navigation Item

←

List ViewResourceGraphical View

Go To Applications

Available Queries

All Records

All Bookmarks

Common Actions

+

New Resource List

Save Resource List

Clear Changes

Delete Resource List

Refresh Resource List

More Actions

Attachment Library/Folders

Duplicate Resource List

Add to Bookmarks

Run Reports

Quick Filter

Graphical Work week

Graphical Work Week

Mike Wilson

Find Scenario

Find Navigation Item

Go To Applications

Available Queries

All Records

All Bookmarks

Common Actions

New Work List

Save Work List

Clear Changes

Delete Work List

Refresh Work List

Roll Project

More Actions

Attachment Library/Folders

Create Work List from Schedule

Create Work List from Graphical Assign...

Duplicate Work List

Add to Bookmarks

Run Reports

Configure Gantt View Properties

List View

Work

Graphical View

Quick Filter

LDN_GWW

Work	Task	Description	Duration	Wo	Resources	Stat
☒	☒	☒	☒	☒	☒	☒
☐	LDNE1158	Electrical and Mechanical	1:15	1	Over Head Line Crew	WAIT
☐	LDND1158	Electrical and Mechanical	1:15	1	Over Head Line Crew	WAIT
☐	LDNA1167	Inspect Tools Control Dra	2:00	1	Over Head Line Crew	WAIT
☐	LDNA1208	Smart Meter Installation	2:00	1	Over Head Line Crew	WAIT
☐	LDNB1296	Electrical Inspection	4:00	1	Over Head Line Crew	WAIT
☐	LDNB1224	Utility Line Repair	1:00	1	Over Head Line Crew	WAIT
☐	LDNE1195	Class 8 Truck	1:30	1	Over Head Line Crew	WAIT
☐	LDNB1163	Install Lay-down Drip Tra	3:00	1	Over Head Line Crew	WAIT
☐	LDNA1300	Utility Line Installation	2:30	1	Over Head Line Crew	WAIT

Jun 2021 W25

Sun/13	Mon/14	Tue/15	Wed/16	Thu/17	Fri/18	Sat/19

Quick Filter

Reason Code

Full Day

Resourc	Description	Allocatio	Skill Level	Shift	Crew Work Gro
☐	CARP	Carpenter			
☐	LDNRANCE	Adena Rance	0%	FIRSTCLASS	DAYS
☐	LDNSCHAF	Brooke Shaffer	3%	FIRSTCLASS	DAYS
☐	LDNSIMMO	Elena Simmonds	0%	FIRSTCLASS	DAYS
☐	ELECT	Electrician			
☐	LDNBODIN	Jeromy Bodine	0%	SECONDCLASS	DAYS
☐	LDNGAITE	Lenard Gaiter	0%	FIRSTCLASS	DAYS
☐	LDNKINNA	Wesley Kinnard	0%	FIRSTCLASS	DAYS
☐	LDNSIMER	Camille Simerly	0%	FIRSTCLASS	DAYS
☐	LDNSTOGS	Rosina Stogsdill	0%	FIRSTCLASS	DAYS
☐	LDNWINEG	Wayne Winegar	0%	FIRSTCLASS	DAYS
☐	LDNZIEME	Mickay Ziemer	0%	FIRSTCLASS	DAYS

Jun 2021 W25

Sun/13	Mon/14	Tue/15	Wed/16	Thu/17	Fri/18	Sat/19
1:00/0:00	14:00/24:00	6:00/16:00	5:30/24:00	8:45/24:00	5:00/24:00	0:00/0:00
0:00	8:00	0:00	8:00	8:00	8:00	0:00
0:00	8:00	7:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
1:00/0:00	9:00/56:00	7:00/56:00	0:00/56:00	0:00/56:00	0:00/56:00	0:00/0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00
0:00	8:00	8:00	8:00	8:00	8:00	0:00

Bijlages aanwezig ??

Bijlagen



Statusdatum:
31-12-98 13:00

Gemeld door:
WINSTON  

Datum gemeld:
31-12-98 9:00 



-  Bijlagen weergeven
-  Nieuwe bijlagen toevoegen 
-  Toevoegen vanuit bibliotheek
-  Nieuw bestand toevoegen
-  Nieuwe webpagina toevoegen

Datum gemeld:
31-12-98 9:00 

Bijlagen



Statusdatum:
31-12-98 13:00

Gemeld door:
WINSTON  

Datum gemeld:
31-12-98 9:00 

Bijlages koppelen en visualiseren

Extra tabblad

← **Lijstweergave** Werkorder Gepland Werkopdrachten Werkelijke waarden Locatie historie **Documenten** Gerelateerde werkorders

Werkorder: 5006 Check-out Alignment of Steel Support Bracket Locatie: BPM3100 #1 Liquid Packaging Line

Documenten [Filteren](#) > 0 - 0 van 0

Document	Beschrijving	Documentmap	Afdrukken?
 Er zijn geen rijen die kunnen worden weergegeven. Nieuw document			

Kleursignalering

← **Lijstweergave** Werkorder Gepland Werkopdrachten Werkelijke waarden Locatie historie **Documenten** Gerelateerde werkorders Kaart


Documenten [Filteren](#) > 1 - 1 van 1

Document	Beschrijving	Documentmap	Afdrukken?
1055	dompelpomp.jpg	Attachments	☒  

Nieuw document

Samenwerking tussen Gamba en Viewport

GEMBA
ASSETMANAGEMENT



- Samenwerking Gemba en Viewport
- Documenten zoeken en bekijken binnen Maximo
- Maximo data beschikbaar binnen viewport

Koppeling met Viewport

GEMBA
ASSETMANAGEMENT



Homepage R4D

Files [Customize](#)

- HSE
- Operating Manual
- Procedures
- Drawings
 - Layouts
 - P&IDs
 - P&ID HIGH PRES:
 - P&ID HIGH PRES:
 - P&ID LOW PRESS
 - P&ID LOW PRESS
 - P&ID WELL-2 - N
 - P&ID WELL-3 - I**
 - P&ID WELL-4 - N
 - P&ID WELL-5 - N
- Red-Blue Markups
- Lists
- Reports
- Pictures
- Vendor
- Well data
- 3D Models
- Movies

Tag Numbers [^](#)

P&ID WELL-3 NL34-B2-31-006-003 Version: 18 Nov 2020 13:16

Search R4D... [Maximize](#) [New tab](#) [Feedback](#) [Share](#) [admin](#)

1 / 1 63.8% [sdv-102](#)

SDV-102 Shut Down Valve

Properties References (4) Maximo Workorders

Inspect: Shut Down Valve

Status: Waiting to be scheduled
Type: INSP
WO num: 1565
WO id: 133624
Asset number: 31000217827
Site id: VIEWPORT
Location: R4D/SDV-102

[Open in Maximo](#)

Inspect: Shut Down Valve

[Go to "SDV-102"](#)

References (49)

- HSE (0)
- Operating Manual (1)
- Procedures (0)
- Drawings (2)
- Lists (0)
- Reports (0)
- Pictures (0)
- Vendor (0)
- Well data (0)
- 3D Models (0)
- Movies (0)
- Tag Numbers (46)
- Other sites (0)

Possible references (11)

- Markup (0)
- QC (0/78)

In folder R4D / Drawings / P&IDs, contains 0 items, last updated 18 Nov 2020 13:16 in FileSystem .PDF show more [^](#)

- Werkorderinformatie binnen viewport
- Inspectie informatie binnen viewport
- Directe link naar Maximo records

Werkorders aanmaken stapsgewijs

Workorder creation

Create new work order

Prioritization

Workorder information

• Work Type:

CM

• Location:

ASSETNL

• Description:

Screenshots

• Period:

• Lead Craft:

CONS

• Duration:

0:00

Next

Create new work order

Prioritization

1. Mitigation

2. Prioritization

2. Consequence Category (P,A,E,R)

Prioritization Matrix

If we don't act, at which aspect can we expect a consequence? "Category" (After mitigation)
Determine this for all four consequence categories and select.
① Goal is to determine which consequences we managing. (could be more than one)

• People:

Y

• Asset:

Y

• Environment:

Y

• Reputation:

Y

People Severity:

P1A

7

Asset Severity:

A2A

6

Environment Severity:

E3A

5

Reputation Severity:

R4A

4

SEVERITY	LIKELIHOOD				
	A	B	C	D	E
1	7	6	5	4	3
2	6	5	4	3	2
3	5	4	3	2	1
4	4	3	2	1	1
5	3	2	1	1	1

3. Consequence Severity

If we don't act, what is the potential severity of the consequence after mitigation.
Use the "Severity" criteria of the Corrective Maintenance Risk Assessment Matrix for all valid categories.
① The potential severity criteria you will find in the category columns of the Corrective Maintenance Risk Assessment Matrix

• People Severity:

1

• Asset Severity:

2

• Environment Severity:

3

• Reputation Severity:

4

The order of Consequence Categories in case the result are equal is : P,A,E,R. E.g. if "P" and "A" Consequence Categories are equal after the prioritisation assessment than the category is set as "P"

Result

Priority:

4

8 Weeks - Routine

4. Likelihood of occurrence

If we don't act, when will the consequence potentially hit us after mitigation? "Likelihood" (E t/m A)
Select the "Likelihood" by means of the severity criteria of the Corrective Maintenance Risk Assessment Matrix.
① Read the Corrective Maintenance Risk Assessment Matrix. "Likelihood" boxes from right "E" to left "A"

Likelihood of occurrence:

A

Previous

Create workorder

© 2017 GEMBA

Werkorders aanmaken stapsgewijs: video

GEMBA
ASSETMANAGEMENT

The screenshot displays the GEMBA ACC Work Orders interface. The browser address bar shows the URL: https://maxacc.infra01.net/maximo/ui/?event=loadapp&value=wetrack&uisessionid=9&_ft=bfd7qg5q4uoecume5ekp3um. The user is logged in as MAXADMIN. The interface includes a sidebar with navigation options and a main content area with a search bar and a table of work orders.

Find Work Order

Find Navigation Item

Go To Applications

Available Queries

- All Records
- All Bookmarks
- Overdue SECE WO's
- Overdue Maintenance Hours
- Overdue Maintenance WO's
- All UR work orders
- All Work Orders
- Asset PC Project Supervisor all Uni...
- Asset PC Project by Status Year 20...
- Asset PC Project by Status Year 20...
- Asset PC Project by Status Year 20...
- Asset PC Project by Status Year 20...
- Asset PC Project by Status Year 20...
- Asset PC Project by Status Year 20...
- Asset PC Project by Status Year 20...
- Asset PC Project by Status Year 20...

Common Actions

- New Work Order
- Sets the filter to the default valu...
- More Search Fields

More Actions

- Assign to New Parent
- Create Work Package
- Select Owner
- Take Ownership

Work Orders

Filter

Advanced Search **Save Query** **Bookmarks**

Work Orders **Filter** > **0 - 0 of 0**

Work Order	Description	Location	PM Number	History?	Work Type	Status	Target Start	Scheduled Start	Duration	Priority	Supervision	Lead Craft	Execution By	Requisit
------------	-------------	----------	-----------	----------	-----------	--------	--------------	-----------------	----------	----------	-------------	------------	--------------	----------

To find records, use the filter fields and then press Enter. For more search options, use the Advanced Search button. To enter a new record, select the Insert icon in the toolbar.

Locatie drilldown 7.6.1

Hiërarchie

- NEEDHAM - Needham Site - OPERATING
 - BOILER - Boiler Room - OPERATING
 - BR200 - HVAC System- Main Office - OPERATING
 - BR230 - Boiler Room Emergency Generator - OPERATING
 - BR300 - Boiler Room Reciprocating Compressor - OPERATING
 - BR400 - Main Boiler- 50,000 Lb/Hr - OPERATING
 - BR430 - Condensate Return Pump- Centrifugal/100GPM/60FTHD - OPERATING
 - BR431 - Motor- 10hp/1750rpm/TEFC/254T Frame/440v/3ph/60hz - OPE
 - 11430 - Centrifugal Pump 100GPM/60FT HD**
 - 23972 - Motor- 10hp/1750rpm/TEFC/254T Frame/440v/3ph/60hz -
 - 11453 - Pakking, mechanisch, zelf-uitlijnend - 1 inch binnendiam. - 1.0
 - 117084 - As - 1 inch diam. - 1.0
 - 12853 - Rotorblad - 4-1/2 inch diam. - 1.0
 - 20778 - Behuizing centrifugaalpomp - 1.0
 - G-1000 - Lager, flensblok, Fafnir- 1 inch binnendiam. - 2.0
 - LF777 - Filter, Olie - 0.0
 - XMP-9500 - Pakking - AR46 - 1.0
 - PM-PUMP - Condensate Return Pump Quarterly Service
 - BR450 - Feed Water Pump- Centrifugal/100GPM/60FTHD - OPERATING
 - BR460 - Burner, Gas Fired- For Boiler - OPERATING
 - 11400 - Boiler- 50,000 Lb/Hr/ Gas Fired/ Water Tube -
 - FLTGAR - Fleet Garages - OPERATING
 - OFFICE - Office Building - Address Unit #2010 Oak St. - OPERATING
 - PACKAGE - Packaging Department - OPERATING

Hiërarchie

PRIMARY

Zoeklocatiehiërarchie:
NEEDHAM

Informatie

Locatie:	NEEDHAM	Needham Site
Status:	OPERATING	In werking
Type:	OPERATING	
Artikel:		
Metergroep:		

Werkgegevens bekijken

Locatie drilldown 7.6.0 (video)

The screenshot displays the GEMBA web application interface. The browser address bar shows the URL: `dmmobile.gemba.nl/maximo/ui/?event=loadapp&value=location&uisessionid=3&_tt=pngaaran75v5tvpjc6romu8ofe`. The application header includes a navigation menu with 'Locaties' and a search bar. The main content area shows a 'Query' dropdown set to 'Locatie zoeken' and an 'Actie selecteren' dropdown. A modal window titled 'Hiërarchie' is open, displaying a tree view of the location hierarchy. The tree view shows 'NEEDHAM' as the selected location, with a list of sub-locations: 'BOILER:Boiler Room', 'FLTGAR:Fleet Garages', 'OFFICE:Office Building - Address Unit #2010 Oak St.', 'PACKAGE:Packaging Department', 'PLANT-P1:Materials Processing Plant #1', and 'SHIPPING:Shipping and Receiving Department'. The modal also includes a 'Systeem' dropdown set to 'PRIMARY' and buttons for 'Alle systemen weergeven', 'Pad naar hoogste niveau weergeven', and 'Werkdetails weergeven'. The 'Status' field is set to 'OPERATING' and the 'Vestiging' field is set to 'BEDFORD'. The modal footer contains an 'Annuleren' button.

Locaties

Query Locatie zoeken Actie selecteren

Uitgebreid zoeken Query

Locaties Filteren

Locatie Beschrijving

Hiërarchie

Kies om de onderliggende niveaus af te beelden. Kies om de onderliggende niveaus te verbergen. Kies om locatie / activum te retourneren.

Locaties Activa

Locatie: NEEDHAM Needham Site Status: OPERATING Vestiging: BEDFORD

Activum op locatie: Op deze locatie zijn geen activa gevonden.

Systeem PRIMARY

Alle systemen weergeven

Pad naar hoogste niveau weergeven

Werkdetails weergeven

NEEDHAM:Needham Site

- BOILER:Boiler Room
- FLTGAR:Fleet Garages
- OFFICE:Office Building - Address Unit #2010 Oak St.
- PACKAGE:Packaging Department
- PLANT-P1:Materials Processing Plant #1
- SHIPPING:Shipping and Receiving Department

Annuleren

Locatie drilldown 7.6.1 (video)

GEMBA
ASSETMANAGEMENT

The screenshot displays the GEMBA Asset Management web application interface. The browser address bar shows the URL: `dmmobile.gemba.nl/maximo/ui/?event=loadapp&value=location&uisessionid=3&_tt=ogl8s3la3qjirbu0bi15llh2e4`. The application header includes the 'Locaties' menu and the user 'MAXADMIN'. The main content area shows a search bar with 'Uitgebreid zoeken' and a list of locations. A modal window titled 'Hiërarchie' is open, displaying a tree view of locations. The tree view shows a hierarchy starting with 'NEEDHAM - Needham Site - OPERATING', which is expanded to show sub-locations: 'BOILER - Boiler Room - OPERATING', 'FLTGAR - Fleet Garages - OPERATING', 'OFFICE - Office Building - Address Unit #2010 Oak St. - OPERATING', 'PACKAGE - Packaging Department - OPERATING', 'PLANT-P1 - Materials Processing Plant #1 - OPERATING', and 'SHIPPING - Shipping and Receiving Department - OPERATING'. The 'IC-67671 - Fire Extinguisher Inspection and Certificate' is listed below the tree. The modal also includes a 'Zoeklocatiehiërarchie:' section with 'NEEDHAM' selected, and an 'Informatie' section showing details for the selected location: 'Locatie: NEEDHAM', 'Status: OPERATING', 'Type: OPERATING', and 'Artikel:'. The 'Informatie' section also shows 'Needham Site' and 'In werking'. At the bottom of the modal are buttons for 'Alle systemen afbeelden', 'Pad naar top afbeelden', 'Werkgegevens bekijken', 'OK', and 'Annuleren'.

Locaties

Query

Uitgebreid zoeken

Locaties

Filteren

Locatie

Beschr

Hiërarchie

NEEDHAM - Needham Site - OPERATING

BOILER - Boiler Room - OPERATING

FLTGAR - Fleet Garages - OPERATING

OFFICE - Office Building - Address Unit #2010 Oak St. - OPERATING

PACKAGE - Packaging Department - OPERATING

PLANT-P1 - Materials Processing Plant #1 - OPERATING

SHIPPING - Shipping and Receiving Department - OPERATING

IC-67671 - Fire Extinguisher Inspection and Certificate

Hiërarchie

PRIMARY

Zoeklocatiehiërarchie: NEEDHAM

Informatie

Locatie: NEEDHAM

Status: OPERATING

Type: OPERATING

Artikel:

Metergroep:

Needham Site

In werking

Alle systemen afbeelden

Pad naar top afbeelden

Werkgegevens bekijken

OK


Annuleren

Positie bepaling

Werkorder:

1013

Inspect and Repair Pump as Required



Lijst weergave via maps
(meerdere werkorders)



Google Maps / Bing maps: 1 werkorder (video)

Werkorders traceren

Query Werkorder zoeken Actie selecteren

Uitgebreid zoeken Query opslaan Bladwijzers

Werkorder	Beschrijving	Locatie	Activum	Status	Geplande start	Prioriteit	Is dynamisch?	Dynamisch taakplan toegepast	Vestiging
4200,1222									=BEDFORD
4200	Annual Pump Maintenance	BR430	11430 ⓘ	COMP	1-3-11 14:00	8	☐	NO	BEDFORD ⓘ
1222	Check out air filter	BR210	11240 ⓘ	COMP	30-3-16 15:00	3	☐	NO	BEDFORD ⓘ

☐ Records selecteren

Google Maps / Bing maps: meerdere werkorders (video)

GEMBA
ASSETMANAGEMENT

Everyplace Technician (Telefoon) x +

dmobile.gemba.nl/maximo/ui/?event=loadapp&value=techphone

Apps Demo 7.6.1 DMOG 7.6.1 WorkCenterDemo (...) Welkom bij Maximo NetScaler Gateway Maximo HSE Applic... Service Details - IB... lineair Welkom bij de nieu... WBR-testomgeving Leeslijst

Everyplace Technician (Telefoon) MAXADMIN

Uitgebreid zoeken Query opslaan

Werkorders Filteren 1 - 2 van 2

Werkorder	Beschrijving
4200	Annual Pump Maintenance
1222	Check out air filter

☐ Records selecteren

1 - 2 van 2

Kaartweergave

Microsoft Bing

Benodigd materiaal 1 - 3 van 3

Records samenvoegen en scrollbaar

GEMBA
ASSETMANAGEMENT

Werklogboek

Communicatielogboek


Work Logs

Filteren


>

WORK LOG	
Samenvatting :	
Werkorder nr. :	AGWWO21/46530
Datum :	29/10/21 4:44
Aangemaakt door :	VR01
Omschrijving :	Batterijen SOC waarde 30 Machine opzetten alles lijkt in orde, generator wilt motor starten maar draait niet mee. Bij opstarten motor met hybride uit start de motor maar komt geen spanning op DC bus. => Koppeling kapot !?
Samenvatting :	
Werkorder nr. :	AGWWO21/46530
Datum :	29/10/21 4:44
Aangemaakt door :	VR01
Omschrijving :	Batterijen SOC waarde 30 Machine opzetten alles lijkt in orde, generator wilt motor starten maar draait niet mee. Bij opstarten motor met hybride uit start de motor maar komt geen spanning op DC bus. => Koppeling kapot !?

Mobile Skin




Workcenters




MOBIEL WERKEN: (OFFLINE) APPS

GEMBA
ASSETMANAGEMENT

Maximo Mobile



EzMaxMobile



MOBIEL WERKEN: GEMBA CUSTOM APPS

GEMBA
ASSETMANAGEMENT

9:41

< Back

🔄

🕒 4:30

W2384

📄

Attachments

View log

Assign

Assetno. E1GG0952A Position no. 10
Infor Id 5.188.0099 Type Machine
Wo - summary
VES Meterreadings
Asset description
Modular Automatic Belt Serv. Incl. INS

Check tires, lights, horn, mirrors

Est time: 01:30 hrs

Materials

Follow up

Photo's

Complete ☒

Video's

Comments

Check tires, lights, horn, mirrors

Est time: 01:30 hrs

Materials

Follow up

Photo's

Complete ☒

Video's

Comments

New SR

My SR ²

Asset Info

9:41

< W2384

🔄

Assetno. E1GG0952A 🕒 4:30
Infor Id 5.188.0099 COR
Wo - summary
VES Meterreadings

Pause

Asset description
Modular Automatic Belt Serv. Incl.
Position no. 10 Type Machine

History

Assign colleague

Info

INSPECTIONTASKS

Measure the radial run-out of the B&T drum

0.40 | 0.20

🚩

📷

📱

💬

Measure the radial run-out of the B&T drum

0.40 | 0.20

🚩

📷

📱

💬

New SR

My SR ²

Asset Info

9:41

< New Service Request

🔄

Projectnumber

Asset

Projectnumber

Asset

Description

Short description

Long description

Photo's / Video's

+

+

+

+

Owner

Choose owner

Customer Contact (optional)

+

SR Type

Prio

SR Type

Prio

Failure Type


Failure Type

Save

CUSTOM DASHBOARDS

GEMBA

ASSETMANAGEMENT





Maximo Reporting

GEMBA
ASSETMANAGEMENT



Ad Hoc

BIRT

Cognos



PowerBI



Tibco Spotfire

